

Drill the center front hole 3/8" up from bottom of

chin piece using a 7/32" drill bit.

STEP 1

3/8

STEP 3

short T-nut

TPC2 MOUNTING INSTRUCTIONS FOR: R Helmet

STEP 2

Drill each side hole.

You will need to measure from the center of the side hook-up screw to the specified location.

WARNING:


See page 2 - R helmet requies new hole in TPC2.

Parts

- 1 TPC2 throat piece,
- 1 short, 2 long t-nuts, 2 silver screws, 2 silver bushings, 1 black screw, 2 black bushings.

Tools Needed

Drill, 7/32" drill bit, ruler, Phillips head screwdriver, marker.



WARNING:

R helmet requies new hole to be drilled in some TPC2's.

